





Number T11971 revision 0 Project number 2448029 Page 1 of 1



Issued by

NMi Certin B.V.,

designated and notified by the Netherlands to perform tasks with respect to conformity assessment procedures mentioned in article 17 of Directive 2014/32/EU, after having established that the Measuring instrument meets the applicable requirements of Directive 2014/32/EU, to:

Manufacturer

Snap-on Diagnostics Denney road King's Lynn Norfolk PE30 4HG United Kingdom

Measuring instrument

Exhaust Gas Analyser

Manufacturer's mark or name: SUN

Type DGA6000 - SGMIII

Further properties are described in the annexes:

- Description T11971 revision 0;

- Documentation folder T11971-1.

Valid until 19 March 2031



Issuing Authority

NMi Certin B.V., Notified Body number 0122 19 March 2021



Certification Board

This document is issued under the provision that no liability is accepted and that the manufacturer shall indemnify third-party liability.

The designation of NMi Certin B.V. as Notified Body can be verified at http://ec.europa.eu/growth/toolsdatabases/nando/

Reproduction of the complete document only is permitted.

This document is digitally signed and sealed. The digital signature can be verified in the blue ribbon at the top of the electronic version of





NMi Certin B.V. Thijsseweg 11 2629 JA Delft The Netherlands T +31 88 636 2332 certin@nmi.nl www.nmi.nl

